

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	3 4 7 9	DATE	December 2, 2014
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	Because the shape of mounting stay for intercooler pipe that connects turbocharger of motor and intercooler is inappropriate, breakage of the mounting stay caused by the resonance of engine may occur. Therefore, the intercooler pipe might be disconnected from the turbocharger and the engine output might be decreased if it keeps using it under such a condition and in the worst case, the turbocharger may damage.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-T181F	「TJV95」	2010-2012	310
	「MF1726」	2012	9
KDP-T180F	「TJV85」	2010-2012	224
	「MF1724」	2012	6
KDP-T179F	「TJV75」	2010-2012	241
	「MF1723」	2012	11
		TOTAL	801