

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3483	DATE	Dec.4.2014
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the passenger side frontal airbag inflator of the subject vehicles, the inflator housing ruptured during preparation for vehicle disposal. While the root cause has not been identified, there is a possibility that inflators of the same type and same model year could rupture during the deployment of the airbag, creating projectile fragments, which could result in a fire or injury to an occupant; therefore, for all affected vehicles, the airbag will be replaced with a new one as a precautionary measure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-NZE121	[COROLLA]	2003	28,939
UA-NZE124	[COROLLA RUNX]		4,771
UA-ZZE122	[ALLEX]		3,416
UA-ZZE124			674
UA-NZE120	[COROLLA]	2003	1,597
KE-CE121			196
TA-ZZE123	[COROLLA RUNX] [ALLEX]		622
UA-NZE121G	[COROLLA FIELDER]		4,829
UA-NZE124G			2,515
TA-ZZE122G			4,138
UA-ZZE122G			
TA-ZZE123G			547
UA-ZZE124G			863
KE-CE121G			103

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-MNH10W	[ALPHARD G]	2003	9,879
TA-MNH15W	[ALPHARD V]		5,560
UA-ANH10W			17,727
UA-ANH15W			4,783
TA-ACM21W	[IPSUM]		10,410
UA-ACM21W			
TA-ACM26W			2,192
UA-ACM26W			
TA-ACT10	[OPA]		191
UA-ZCT15			647
TA-ACM10G	[GAIA]		886
TA-ACM15G			881
KH-CXM10G		2002 – 2003	52
TA-AZR60G	[NOAH]	2003	17,947
TA-AZR65G	[VOXY]		11,781
TA-JCG10	[BREVIS]		2,115
TA-JCG11			570
TA-JCG15			323
UB-NCP50V	[PROBOX]		2,730
UA-NCP58G	[PROBOX]		1,818
UA-NCP59G	[SUCCEED]		1,380
UB-NCP51V			7,488
UB-NCP55V			2,598
KP-NLP51V			573
TA-JZX115	[MARK II]		384
GH-JZX110	[MARK II]		3,979
TA-JZX110	[VEROSSA]		
TA-GX110			9,443
TA-GX115			1,296

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-JZX110W TA-JZX110W	[MARK II BLIT]	2003	1,062
TA-GX110W			1,617
TA-GX115W			359
TA-JZX115W			216
UA-NCP70			[WILL CYPHA]
UA-NCP75		1,181	
TA-NZE127 UA-NZE127	[WILL VS]	2002 – 2003	425
TA-ZZE127			281
TA-ZZE128			163
TA-ZZE129		74	
		TOTAL	185,093