

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3487	DATE	December 9 ,2014
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	As heat treatment method of the tappets for the wheel cylinders in the rear brake system of medium duty trucks is inappropriate, some tappets in question have insufficient strength. As a result, there is a danger that the tappets may be broken as they cannot withstand a braking force pressure, brake fluid may leak from the wheel cylinders and a braking force may be reduced.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-FRR90S2	[FORWARD]	2014	3
SKG-FSR90T2		2014	1
SDG-GSR90S2		2014	1
		TOTAL	5