

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

| | | | |
|-----------------------|--|------|---------------|
| CAMPAIGN No. | Gai-2126 | DATE | Dec. 11. 2014 |
| MANUFACTURE | BMW (Japanese Importer: BMW Group Japan Corp.) | | |
| DESCRIPTION OF DEFECT | BMW Motorrad has ascertained that when latched, the rocker switch in the right multifunction switch assembly can stick in the EMERGENCY OFF position. If this happens considerable pressure subsequently has to be applied to operate the starter button. In rare cases this can mean that it is not possible to start the engine. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-----------|-----------------|---------------------|-------------------|
| C600S | BMW C600S | 2014 | 39 |
| C650GT | BMW C650GT | 2014 | 77 |
| EBL-R12JB | BMW R nineT | 2014 | 226 |
| HP 4 | BMW HP 4 | 2014 | 43 |
| S1000RR | BMW S1000RR | 2014 | 18 |
| S1000R | BMW S1000R | 2014 | 167 |
| EBL-K16AA | BMW K1600GT | 2014 | 9 |
| EBL-K16AA | BMW K1600GTL | 2014 | 11 |
| EBL-K16AA | BMW K1600GTL-E | 2014 | 141 |
| EBL-R12NA | BMW R1200GS | 2014 | 195 |
| EBL-R12NA | BMW R1200GS-A | 2014 | 70 |
| EBL-R12NA | BMW R1200RT | 2014 | 110 |
| F700GS | BMW F700GS | 2014 | 113 |
| F800GT | BMW F800GT | 2014 | 59 |
| F800GS | BMW F800GS | 2014 | 20 |
| F800R | BMW F800R | 2014 | 15 |
| F800GS-A | BMW F800GS-A | 2014 | 15 |
| | | TOTAL | 1,328 |