

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	3489	DATE	December 11, 2014
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the inflator for the passenger-side airbag, we have obtained the information from the supplier that the container of the inflator was ruptured at the time of disassembly process of the scrap vehicle manufactured by the other car manufacture. As a result, the airbag module or the inflator will be replaced with a newly manufactured one for investigation purpose since it may be possible that the occupants may be injured or the vehicle may catch fire by the flying fragment caused by the ruptured inflator at the time of the airbag deployment in the vehicle with a inflator of the same type and model year, as the root cause of the problem is not known yet.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-CS2A	「LANCER」	2003	7
UB-CS2V		2003	274
LA-CS5A		2003	1
UA-CS5AR		2003	21
LA-CS5W		2003	1
		TOTAL	304