

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2128	DATE	December 19 th , 2014
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The ground bolt welded to the fuel tank might have been welded incorrectly, which may lead to damage the welding surface. Thus, fuel may leak at the fuel tank, and in the worst case, fire could occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DLA-2Z15	「BMW i8」	2014	12
		TOTAL	12