

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3496	DATE	Jan, 13, 2015
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	<p>(1) The outer case of the electric valve for direction control is not adequate , It leads to malfunction of the valve due to contamination. Consequently, it makes opposite tractor movement against the speed lever or stop movement.</p> <p>(2) The electric wire harness for the engine control may contact the bonnet link, so that makes the wire harness damage. Consequently, the worse case scenario, the engine may be shut off.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-KL3N	「KL31Z」	2013~2014	377
	「KL34Z」	2013~2014	761
EDM-KL3K	「KL37Z」	2013~2014	736
	「KL40Z」	2011~2014	1,539
	「KL44Z」	2011~2014	2,252
	「T2200KLZ」	2011~2014	292
EDM-KL3L	「KL48Z」	2011~2014	1,092
KDN-KL3M	「KL53Z」	2011~2014	2,954
	「KL58Z」	2011~2014	1,584
		TOTAL	11,587