

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3488	DATE	Jan. 15, 2015
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Regarding accelerator cable, due to the cause such as an alumina powder was mixed in a liner, an inner cable may wear earlier than usual. Therefore, the inner cable may fray and get stuck with the liner, which prevent engine speed from lowering. Also, the inner cable may break which results in eventual disability of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-TT1 GBD-TT1	「SAMBAR」	2011	3,262
EBD-TT2 GBD-TT2		2011	24,552
EBD-TV1 GBD-TV1		2011	5,569
EBD-TV2 GBD-TV2		2011	6,503
		TOTAL	39,886