

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3500	DATE	January 15, 2015
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>As the belt tensioner that drives engine accessories has an insufficient aspect of construction, the pulley of the tensioner may tilt with tension of the belt. That can make the belt skid and pull off while the engine is working. The belt pulling off results stopping of the alternator and the water pump with the warning lamp on. In the worst case the engine might stop and could not restart.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-RE91S	KIZASHI	2013 to 2014	90
CBA-RF91S		2013 to 2014	55
		TOTAL	145