

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 5 0 7	DATE	Jan.29.2015
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Due to an inappropriate roundness of the outer tube in the steering column, the load to the inner bearing may be uneven. If the vehicle continues to be driven in this condition, the bearing will be damaged and the play for up and down direction of steering may grow, in an extreme case, the steering wheel may not be able to fix for the back and forth direction.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBA-R35	GT-R	2007~2008	2,893
		TOTAL	2,893