

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3510	DATE	Jan. 29 2015
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty sightseeing buses, if the turn signals are operated for a long time repeatedly, the upper portion of the orange cap in the rear turn signal unit may melt. If the bus continues to be used in this condition, the portion will melt down to make a hole and the vapor from the cap will cloud the inside of the turn signal lens.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-MM96FH	「FUSO AERO ACE」	2008~2011	259
LDG-MM96FH		2011~2012	6
SDG-MM96FH		2011~2012	28
QDG-MM96FH		2012~2014	29
TDG-MM96FH		2012~2014	131
QDG-MM97FH		2014~2014	6
TDG-MM97FH		2014~2014	25
BKG-MS96JP			2007~2010
	「FUSO AERO QUEEN」	2007~2010	338
LKG-MS96VP	「FUSO AERO ACE」	2010~2012	469
	「FUSO AERO QUEEN」	2010~2012	93
QRG-MS96VP	「FUSO AERO ACE」	2012~2015	1,503
	「FUSO AERO QUEEN」	2012~2014	194
PDG-AM96FH	「SPACEARROW A」	2008~2011	13
BKG-AS96JP		2007~2010	58
		「SPACEWING A」	2007~2010
LKG-AS96VP	「SPACEARROW A」	2010~2011	12
	「SPACEWING A」	2010~2011	5
		TOTAL	4,509