

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3504	DATE	January 30, 2015
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Open circuit as a malfunction may occur on the electric board in the LED unit of the auxiliary brake light, due to insufficient engineering of the board inviting corrosion on it. Therefore the auxiliary brake light can potentially stop lighting if used continuously as it is.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-MH34S	WAGON R	From 2012 to 2013	76,720
DBA-MJ34S	FLAIR		8,368
		TOTAL	85,088