

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3 5 2 0	DATE	February 13,2015
MANUFACTURER	KCM Corporation		
DESCRIPTION OF DEFECT	In the silencer of the wheel loader, there is possibility that the brackets fixing bolts might be broken and the motor accessory bracket might be cracked because insufficient strength of the mounting brackets, the brackets fixing bolts and the motor accessory bracket. And the exhaust pipe might be cracked because inadequate assembly of the exhaust pipe and the mounting brackets. If it is used continually as this condition, the exhaust pipes might be damaged by vibration of the silencer.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-65J4	「65ZV-2」	2008-2013	456
EDR-RM06	「LK190Z-6」	2008-2013	21
EDR-A4SDT50	「4SDT50」	2009-2013	10
TOTAL			487