

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	3515	DATE	February 13, 2015
MANUFACTURE	SUMITOMO NACCO MATERIALS HANDLING CO., LTD. (Japan)		
DESCRIPTION OF DEFECT	For the rear wheel bearing was assembled by incorrect pressurization, flaking might be occurred on the raceway of the bearing. And when the truck is used for a long term in the state, the bearing is damaged and the rear hub might come off from the truck.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-D1G	FD15PXI	2013	1
EDM-D2K	FD25PXI	2011 ~ 2013	4
KDN-D2L	FD25PXI	2010 ~ 2013	14
KDN-D3H	FD30PXI FD35PXI	2010 ~ 2013	33
EBT-G2K	FG25PXI FL20PXI FL25PXI	2010 ~ 2012	3
EBT-G3G	FG30PXI FL30PXI	2010 ~ 2013	7
EDM-SD1E	FD10PXI, FD14PXI FD15PXI, FD18PXI FD20PXI	2010 ~ 2013	61
EDM-SD2E	FD20PXI FD25PXI	2010 ~ 2013	125
EBT-SG1J	FG09PXI, FG10PXI FG14PXI, FG15PXI FG18PXI, FG20PXI FL10PXI, FL15PXI FL18PXI, FL20PXI	2010 ~ 2013	104

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBT-SG2H	FG20PXI, FG25PXI FL20PXI, FL25PXI	2010 ~ 2013	78
SG3A	FG30PXI FG35PXI FL30PXI	2010 ~ 2013	5
SD3	FD30PXI FD35PXI	2011 ~ 2013	7
B1H	FB15PE	2011	1
B2H	FB20PE FB25PE	2010 ~ 2011	3
SB1H	FB09PSE, FB10PSE FB14PSE, FB15PSE FB18PSE, 8FB15PS	2010 ~ 2012	129
ZAF-SB1J	FB09PSE, FB10PSE FB14PSE, FB15PSE FB18PSE	2012 ~ 2013	40
SB2H	FB15PGS, FB15PJS FB20PSE, FB25PSE 8FB25PS	2010 ~ 2013	64
ZAF-SB2J	FB20PSE FB25PSE	2013	8
SB3C	FB25PGS FB30PSE 8FB30PS NV1M3L30	2010 ~ 2013	14
		TOTAL	701