

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2149	DATE	February 13 th , 2015
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	There is a possibility that the wiring harness and the connector pin at the fuel delivery unit was inappropriately crimped. Thus, it might lead electrical resistance increase and overheating of the respective area. Then finally fuel leakage can happen.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-FP25	BMW 523i	2010	3,592
DBA-MT25	BMW 523i Touring	2010-2011	1,286
DBA-FR30	BMW 528i	2010-2011	3,420
DBA-MU30	BMW 528i Touring	2010-2011	645
CBA-FR35	BMW 535i	2010-2011	1,287
DBA-MU35	BMW 535i Touring	2010-2011	151
CBA-SN30	BMW 535i GT	2009-2011	654
ABA-FR44	BMW 550i	2010-2011	162
ABA-SN44	BMW 550i GT	2009-2011	98
ABA-SP44	BMW 550i xDrive GT	2010-2011	6
DBA-LW30	BMW 640i Cabriolet	2010-2011	101
ABA-LZ44	BMW 650i Cabriolet	2010-2011	55
ABA-FE30	BMW X5 3.0si	2007-2010	3,798
ABA-FE48	BMW X5 4.8i	2007-2010	783
ABA-ZV30	BMW X5 xDrive 35i	2010	331
ABA-ZV44	BMW X5 xDrive 50i	2010	10
ABA-ZV44S		2010	2
ABA-GY44	BMW X5 M	2009-2010	38
ABA-FG30	BMW X6 xDrive 35i	2008-2010	842
ABA-FG35		2010	102
ABA-FG44	BMW X6 xDrive 50i	2008-2010	225
ABA-GZ44	BMW X6 M	2009-2010	48
		TOTAL	17,636