

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 5 1 7	DATE	Feb.12.2015
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>1)Due to the inappropriate productin and shape of the seal in the high pressure fuel pump with the direct-injection turbo deisel engine, the seal may crack. If the vehicle continue to be driven in this conditon, the crack progresses and penetrates, in an extreme case, the deisel fuel might leak.</p> <p>2)Due to the inappropriate structure of the ABS sensor mount of the rear wheel of the vehicles with the ABS, the seal performace may low. Therefore the maddy water inveded from the seal part arrives in the bearing, if the vehicles continue to be driven in this conditon, the bearing will become poor in lubrication, in an extreme case, the bearing will be damaged and the rear wheel axle shaft may come out and the vehicles might not be able to drive.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ADF-VWE25 LDF-VWE25	N I S S A N C A R A V A N	2 0 0 7 ~ 2 0 1 2	11, 213
ADF-VWME25 LDF-VWME25			5, 961
CBF-VRE25			3, 419
ADF-CWGE25 LDF-CWGE25			1, 884
ADF-CWMGE25 LDF-CWMGE25			2, 066
CBF-CSGE25			1, 193
CBA-SGE25			2, 981
CBA-SE25			596

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES		
CBF-DSGE 25	NISSAN CARAVAN	2007 ~ 2012	2,529		
ADF-DWMGE 25			1,434		
ADF-DWGE 25 LDF-DWGE 25			329		
ADF-JVWE 25 LDF-JVWE 25	ISUZU COMO		1,021		
ADF-JVWME 25 LDF-JVWME 25			422		
CBF-JVRE 25			37		
ADF-JCWGE 25 LDF-JCWGE 25			125		
ADF-JCWMGE 25 LDF-JCWMGE 25			73		
CBF-JCSGE 25			11		
CBA-JSGE 25			14		
CBA-JSE 25			6		
CBF-JDSGE 25			5		
ADF-JDWMGE 25			7		
ADF-JDWGE 25 LDF-JDWGE 25			8		
				TOTAL	35,334