

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3513	DATE	Feb. 5, 2015
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the Steering system of the subject vehicles, due to improper setting position of the equipment for welding the intermediate shaft, which connects the steering wheel to the steering gear box, there is a possibility that the joint portion of the intermediate shaft could be improperly welded. If the vehicle is operated continuously in this condition, the joint portion could become damaged, resulting in loss of steering.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-GSJ15W	[FJ CRUISER]	2013	121
		TOTAL	121