

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3536	DATE	31 Mar 2015
MANUFACTURE	Hitachi Construction Machinery Co.,Ltd.		
DESCRIPTION OF DEFECT	<p>When using the diff-lock, the pressure of the hydraulic circuit can become high. This can cause the excess load on the travel motor of the road roller.</p> <p>If the diff-lock is used quite frequently, the bearing of the travel motor can be worn out quicker, which can break the travel motor and stop the machine.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-CP220	「CP220-3」	2009~2011	8
KDP-N22A2	「HN220WHH-2」	2010	1
		TOTAL	9