

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3540	DATE	March 31 ,2015
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>On certain heavy duty buses, due to the insufficient strength of a bracket of an EGR (Exhaust Gas Recirculation) pipe installed in the engine, there are some a crack is generated into the bracket resonates in a specific engine rotation region. If the vehicle is operated under the condition continuously, the crack of the bracket progresses and the fixing bracket breaks, causing an EGR pipe to crack, which may result in a leak of exhaust gas. In the worst case, there is a possibility that a part of floor is damaged by exhaust gas.</p>	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
LDG-RU8JHBJ SDG-RU8JHBJ	[ISUZU GALA]	2012-2015	150
		TOTAL	150

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
SDG-RU8JHBJ	[ISUZU GALA]	2010-2011	6
		TOTAL	6