

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3530	DATE	Mar. 31, 2015
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>Due to the inappropriate control of front brake caliper installation process, some caliper mounting bolts are insufficiently tightened.</p> <p>If the vehicle is used continuously with this condition, the bolt looses and abnormal noise occurs when braking, in the worst case, the bolt comes off and braking force may decline.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA600S	TANTO	2014-2015	5,812
DBA-LA610S			1,269
DBA-LA100S	MOVE	2014	11
DBA-LA110S			9
DBA-LA150S		2014-2015	2,757
DBA-LA160S			552
DBA-LA100F	STELLA	2014	1
DBA-LA110F			5
DBA-LA150F		2014-2015	450
DBA-LA160F			163
		TOTAL	11,029