

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	3534	DATE	26th . March . 2015
MANUFACTURER	Nichijo Manufacturing Co., Ltd.		
DESCRIPTION OF DEFECT	<p>In the circuit for supplying power to the engine controller, There is an incorrect wiring terminal fixing bolt to the power fuse that was used. Therefore, the fixing bolt is to interfere with the partition wall of the fuse holder, the fastening of the wiring terminals is not supplied power becomes insufficient. In the worst case, there is a risk that the engine stops running.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-R03D	「HTR306」	2013~2014 R03D-0093~ R03D-0128	24
TOTAL			24

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.