

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 5 2 8	DATE	M a r . 2 4 . 2 0 1 5
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As the length of the electric wire and its routing are inappropriate in some devices to prevent forgetting to kick the side stand up, the said electric wire and the rear wheel driving chain contact each other. Therefore, if it is used continuously, the said electric wire may be worn due to a contact with the rear wheel driving chain. In the worst case scenario, the said electric wire may be disconnected and the safety device will activate to prevent forgetting to kick the side stand up, and as a result, the engine may stop while running.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
J BK-RG10J	Y Z F - R 2 5	2 0 1 4 ~ 2 0 1 5	3, 7 3 9
		TOTAL	3, 7 3 9