

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3524	DATE	Mar.17 2015
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On heavy- or medium-duty regular-service buses, tightening force of the bolts that secure the part connecting the door engine to the mid sliding door is improper, and the bolts may loosen and stick out. If the bus continues to be used in this condition, protruded bolts will interfere with the inner pillar, causing faulty operation of the sliding door.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-MP35FM	「FUSO AERO STAR」	2014～2014	2
QDG-MP35FP		2014～2014	4
QKG-MP35FK		2014～2014	3
QKG-MP35FM		2014～2014	24
QKG-MP35FP		2014～2014	7
QKG-MP37FK		2014～2014	68
QKG-MP37FM		2014～2014	42
QKG-MP38FK		2014～2014	8
QKG-MP38FM		2014～2014	2
TKG-MK27FH	「FUSO AERO MIDI」	2014～2014	31
		TOTAL	191