

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3551	DATE	Apr. 14 2015
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty sightseeing buses, the power steering fluid temperature may exceed the heat-resistant temperature of the return hose due to variation in an ejection of power steering oil pump. If the bus continues to be used in this condition, the return hose may come off the power steering oil tank and the steering effort will increase.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-MS96VP	「FUSO AERO ACE」	2010~2012	484
	「FUSO AERO QUEEN」	2010~2012	78
QRG-MS96VP	「FUSO AERO ACE」	2012~2015	1,569
	「FUSO AERO QUEEN」	2012~2015	194
LKG-AS96VP	「SPACEARROW A」	2010~2011	12
	「SPACEWING A」	2010~2011	5
		TOTAL	2,342