

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3535	DATE	APR 2, 2015
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to improper moisture control at the production of Power module (Circuit board) in Regulate Rectifier, if engine being hold at high rpm after long-time idling, Power module is detached from Regulate Rectifier body with cooling fins and the temperature of regulating device in Power module is over its heat resistance temperature.</p> <p>If continued to use with this condition, this can cause discharge of the battery. In the worst case, it can lead to engine stalling during running and be impossible to restart.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BA-CJ44A	SKYWAVE	2007	2,340
JBK-CJ45A		2007~2009	8,757
JBK-CJ46A		2008~2009	14,377
BC-CK44A		2008	1,568
EBL-CK45A		2009	879
		TOTAL	27,921