

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3581	DATE	May.28. 2015
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As regards certain driver's SRS airbag inflators, abnormal rise in internal pressure of the inflator can occur in the event of the airbag deployment whereby the container of the inflator could break and scatter the inflator component parts around, causing injury to the vehicle occupant.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-RR1	「ELYSION」 「ELYSION PRESTAGE」	2004～2013	43,057
DBA-RR2			7,683
DBA-RR3	「ELYSION」	2004～2010	11,568
DBA-RR4			3,434
DBA-RR5	「ELYSION PRESTAGE」	2006～2013	3,631
DBA-RR6			765
		TOTAL	70,138