VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	3572	DATE	22 May, 2015	
MANUFACTURER	SAKAI KIKOH CORPORATION			
DESCRIPTION OF DEFECT	In the water pump's engines for the water sprinkler trucks, due to irrelevant cam's figure, there is a possibility of the engine rotating if it is suddenly placed at its max RPM just before it would normal down. Therefore, the element inside the air cleaner and the air cleaner of involve the risk of being damaged by fire due to hot exhaust gasse sent back into engine's intake.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-XZU700X	HINO DUTRO	2013,2014,2015	46
BDG-FC6JCWA	HINO RANGER	2014,2015	4
TKG-FD9JEAA		2015	1
SKG-NPR85YN	ELF	2013,2014	12
TKG-NPR85YN		2015	9
KK-NRR35C3	FORWARD JUSTON	2013	2
TKG-FRR90S1	FORWARD	2013,2014,2015	50
TKG-FEB90	FUSO CANTER	2013,2014	8
PA-FK71DC	FUSO FIGHTER	2013	1
PDG-FK71D		2014	12
		TOTAL	145