

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2171	DATE	May. 22. 2015
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	BMW Motorrad has ascertained that in the framework of maintenance work on brake discs or wheel changes, threaded fasteners might have been over tightened to torques not in compliance with the values set out in the repair instructions or operating instructions. Cracks in the wheel flange can occur as a consequence of over tightening of threaded fasteners. In the course of a lengthy service life the cracks can propagate and, under worst-case conditions, lead to fracture of the bolted join.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HP2	HP2 Enduro	2005-2006	175
HP2 MM	HP2 Megamoto	2007-2008	122
HP2 SP	HP2 Sport	2008-2010	149
K1200GT	K1200GT	2006-2008	467
K1200R	K1200R	2005-2008	605
K1200R Sport	K1200R Sport	2007	213
K1200S	K1200S	2005-2008	1211
K1300GT	K1300GT	2009-2010	230
K1300R (EBL-K13AA)	K1300R	2009-2011	376
K1300S (EBL-K13AA)	K1300S	2009-2011	519
R1200GS	R1200GS	2004-2010	2553
R1200GS-A	R1200GS Adv	2006-2010	1110
R1200R	R1200R	2006-2010	875
R1200RT	R1200RT	2005-2010	1989
R1200S	R1200S	2006-2007	301
R1200ST	R1200ST	2005-2008	879
		TOTAL	11,774