

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3573	DATE	May 21 ,2015
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	The mid-duty trucks have battery cables of which branching points located midway, are not waterproofed perfectly. For this reason, water may intrude in the branching points to make the terminals corroded. If the trucks are kept in operation under such a condition, there is a possibility that the corrosion will be progressed until the terminals will be broken, and in the worst case, the batteries will be disconnected letting the engines stop and become inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-FRR34S2 PDG-FRR34T2	[FORWARD]	2007-2011	8,283
PKG-FRR90S1 PKG-FRR90S2 PKG-FRR90T2 SKG-FRR90S1 SKG-FRR90S2 SKG-FRR90T2 TKG-FRR90S1 TKG-FRR90S2 TKG-FRR90T2		2007-2014	71,359
PDG-FRS90S1 PDG-FRS90S2 PKG-FRS90S2 SDG-FRS90S1 SDG-FRS90S2 SKG-FRS90S2		2007-2014	393
PKG-FSR34S2 PKG-FSR34T2 SKG-FSR34S2 SKG-FSR34T2 TKG-FSR34S2 TKG-FSR34T2		2007-2013	2,059
PKG-FSR90S2 PKG-FSR90T2 SKG-FSR90S2 SKG-FSR90T2 SPG-FSR90S2 SPG-FSR90T2		2007-2014	4,242
PDG-FSS90S1 PDG-FSS90S2 PKG-FSS90S2 SDG-FSS90S1 SDG-FSS90S2 SKG-FSS90S2		2007-2014	661

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-FTR34S2 PDG-FTR34T2 LDG-FTR34S2 LDG-FTR34T2 LKG-FTR34S2 LKG-FTR34T2 QKG-FTR34S2 QKG-FTR34T2	[FORWARD]	2007-2014	5,309
LKG-FTR90S2 LKG-FTR90T2		2010-2014	3,673
PDG-FTS34S2 LDG-FTS34S2 LKG-FTS34S2 QKG-FTS34S2		2007-2014	184
PDG-FVR34U2 LKG-FVR34U2 QKG-FVR34U2		2007-2014	632
PDG-FVZ34U2 LDG-FVZ34U2 LKG-FVZ34U2 QDG-FVZ34U2 QKG-FVZ34U2		2007-2014	1,495
PDG-GSR34S2		2007-2011	31
SDG-GSR90S2		2011-2014	56
		TOTAL	98,377