

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 5 7 0	DATE	May.21.2015
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Due to inappropriate sealing structure at the tightening area of the cylinder of actuator for the pop-up engine hood, the water may enter into the actuator. As a result, the pop-up engine hood may not be lifted adequately at a frontal vehicle collision. In an extreme case, the vehicle may not meet the requirements of local regulations for the head or leg protection of the pedestrian.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-CKV36	SKYLINE	2007~2008	4,408
CBA-R35	GT-R		2,462
		TOTAL	6,870