

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3571	DATE	May.14. 2015
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>The inflator of the driver's SRS airbag may have been placed under inadequate moisture absorption control after it was filled with gas generating propellant during the inflator manufacturing process. In such an inflator, gas generating propellant may expand and become less dense than usual under the influence of external factors such as outside temperature whilst in use. Such gas generating propellant can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator by which the container of inflator could be broken and scattered about, causing injury to the vehicle occupant.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-JD1	「THAT'S」	2002~2003	10,201
		2002~2003	1,525
		2003	55
LA-JD2		2002~2003	1,470
		2002~2003	436
		2003	15
		TOTAL	13,702