

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3564	DATE	May.13.2015
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the driver side frontal airbag inflator, the investigation results of the recovered inflator from the field showed that some of the recovered inflators had insufficient air sealing. In this condition, the inflators may have a potential for the intrusion of moisture over time. As a result, there is a possibility that the driver side frontal airbag may deploy abnormally.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-NCP10 CBA-NCP10	[Vitz]	2003-2005	1,274
UA-NCP13 CBA-NCP13			1,931
UA-NCP15 CBA-NCP15		2003-2004	5,495
UA-SCP10 CBA-SCP10		2003-2005	15,616
UA-SCP13 CBA-SCP13			16,344
UA-ACA20W CBA-ACA20W	[RAV4J] [RAV4L]	2003-2005	1,178
UA-ACA21W CBA-ACA21W			7,711
UA-ZCA25W CBA-ZCA25W			893
UA-ZCA26W CBA-ZCA26W			5,803
		TOTAL	56,245