

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2170	DATE	May. 12. 2015
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	BMW Motorrad has ascertained that when latched, the rocker switch in the right multifunction switch assembly can stick in the EMERGENCY OFF position. If this happens considerable pressure subsequently has to be applied to operate the starter button. In rare cases this can mean that it is not possible to start the engine.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-K16AA	BMW K1600GT	2012-2013	67
EBL-K16AA	BMW K1600GTL	2011-2013	410
EBL-K16AA	BMW K1600GTL-E	2013-2014	5
K1300S	K1300S	2008-2010	290
EBL-K13AA	K1300S	2010-2013	128
K1300R	K1300R	2008-2010	183
EBL-K13AA	K1300R	2010-2013	128
K1300GT	K1300GT	2008-2010	141
R1200RT	R1200RT	2009-2010	187
EBL-R12JA	R1200RT	2010-2013	399
EBL-R12NA	R1200GS	2013	1
EBL-R12NA	R1200GS-A	2013	2
EBL-R12NA	R1200RT	2013	1
EBL-R12JB	R Nine T	2014	1
S1000RR	S1000RR	2009-2014	623
HP4	HP4	2014	2
C600S	BMW C600S	2012-2014	170
C650GT	BMW C650GT	2012-2014	230
F700GS	BMW F700GS	2012-2014	245
F800GT	BMW F800GT	2012-2014	155
F800GS	BMW F800GS	2012-2014	127
F800R	BMW F800R	2009-2014	421
		TOTAL	3,916