

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 5 9 6	DATE	Jun.25.2015
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Due to inappropriate installation of the reinforcing plate for body under the floor in NISMO version vehicles, the tightening bolts may be under torqued. For the reason, if the vehicle continues to be driven in this condition, the bolts may loose by the vibration while driving, in an extreme case, the reinforcing plate may fall off the floor, and may hinder the traffic.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-E12	NOTE	2014	1,589
DBA-E12KAI		~ 2015	1,363
		TOTAL	2,952