

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 5 9 4	DATE	Jun.25.2015
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Due to the insufficiency of the durability on the pin connecting plates in the timing chain of the engine, the surface treatment of the pin may be worn. If the vehicle continues to be driven in this condition, the pin insertion hole will be worn, and the timing chain will lengthen, and the noise occur by the interference with the chain guide. In an extreme case, the timing chain may break and this can result in an engine stall.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBA-NF15	JUKE	2010	5,585
CBA-F15		~ 2012	2,399
		TOTAL	7,984