

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|--|------|--------------|
| CAMPAIGN No. | 3591 | DATE | June.25.2015 |
| MANUFACTURER | TOYOTA | | |
| DESCRIPTION OF DEFECT | In the passenger side frontal airbag inflator of the subject vehicle, while the root cause has not been identified, there is a possibility that inflator could rupture during the deployment of the airbag; therefore, for all affected vehicles, the airbag will be replaced with a new one as a precautionary measure. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------------------------|---------------------|---------------------|-------------------|
| UA-UZZ40 CBA-UZZ40 | [SOARER] | 2003-2005 | 1,364 |
| ZA-ATH10W | [ALPHARD HYBRID] | 2003 | 3,615 |
| UP-NCP52V | [PROBOX] | 2003 | 45 |
| DBA-UZZ40 | [SC430] | 2005-2007 | 3,079 |
| UA-AZT250 CBA-AZT250 | [AVENSIS] | 2003-2008 | 16,428 |
| CBA-AZT251 | | 2005-2008 | 3,142 |
| UA-AZT255 CBA-AZT255 | | 2003-2008 | 2,429 |
| UA-AZT250W CBA-AZT250W | [AVENSIS WAGON] | 2003-2008 | 10,641 |
| CBA-AZT251W | | 2005-2008 | 3,023 |
| UA-AZT255W CBA-AZT255W | | 2003-2008 | 2,578 |
| TOTAL | | | 46,344 |