

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3603	DATE	June. 25. 2015
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>Engine starting system may have been improperly filled with sealant for waterproofing of starter magnetic switch whereby such sealant may enter the terminal to which the starter magnetic switch fuse is assembled. During the course of use, sealant entered the terminal becomes soft and causes decline in contact pressure at the fuse terminal, thereby increasing contact resistance and generating heat. During the course of continued use in such a condition, the fuse-assembled area can suffer meltdown damage and cause poor electrical continuity, when the engine could stall and refuse to restart or the starter magnetic switch circuit could be short-circuited, resulting in fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-NC42	「CB400 SUPER FOUR」 「CB400 SUPER BOLD'OR」	2013～2015	5,773
EBL-SC54	「CB1300 SUPER FOUR」 「CB1300 SUPER BOLD'OR」	2013～2015	2,674
EBL-RC72	「NC750X」	2013～2015	2,660
JBK-MC33	「VTR」 「VTR-F」 「VTR Type LD」	2013～2015	2,438
EBL-NC47	「CBR400R」 「CB400F」 「400X」	2013～2015	2,066
EBL-RC82	「NM4」	2013～2015	1,578

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-RC70	「NC750S」	2013～2015	1,099
EBL-RC83	「CB650F」 「CBR650F」	2013～2015	1,016
EBL-RC67	「NC750L」	2013～2015	703
EBL-SC62	「CB1300P」	2014～2015	332
EBL-RC71	「INTEGRA」	2014～2015	239
EBL-RC53	「SHADOW PHANTOM」	2013～2015	220
EBL-PC40	「CBR600RR」 「CBR600RR ABS」	2013～2015	210
EBL-RC69	「CTX700」	2013～2015	168
EBL-NC44	「SHADOW CLASSIC」	2013～2015	145
EBL-PF02	「SILVERWING GT」	2013～2015	134
EBL-RC63	「NC700X」	2013	90
EBL-NC45	「SHADOW CUSTOM」	2013～2015	61
EBL-RC50	「SHADOW」	2013～2015	92
EBL-RC56			
EBL-SC61	「VT1300CX」	2013～2015	53
EBL-RC61	「NC700S」	2013	43
EBL-RC68	「CTX700N」	2014	31
EBL-SC67	「VT1300CS」	2013～2014	7
		TOTAL	21,832