

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3598	DATE	JUN. 18. 2015
MANUFACTURER	NIPPON SHARYO.LTD.		
DESCRIPTION OF DEFECT	<p>On tank vehicles, due to insufficient welding strength of the ribs on sub-frame mounting the suspension brackets and the stress brought by breaking, the cracks may occur near the welding line.</p> <p>So. if the vehicles are continued to run without the repairing, at worst case, the suspension brackets come off and it may become to be impossible that the vehicles run.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ATL110-LNG	LNG tank semi-trailer	ATL110LNG-1~22 May.8 2012~Sep.10 2007	22
		ATL110LNG-50~57 Nov.12 2004~Dec.20 2005	1
TOTAL			30