

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2186	DATE	June 4 th , 2015
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The electric fuel pump may be contaminated due to inappropriate manufacturing. Thus, when keep driving under such condition, the contamination could be pressed into the impeller of the pump, and the pump may stop operation. In the worst case, the engine may stall and fail to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-1A16	BMW 116i	2012 - 2014	5,203
DBA-1A16	BMW 120i	2012 - 2014	431
DBA-1B30	BMW M135i	2013 - 2014	225
DBA-1J20	BMW 220i	2014	42
DBA-1J30	BMW M235i	2013 - 2014	221
DBA-3B20	BMW 320i	2013 - 2014	1,461
DBA-3X20	BMW 320i Granturismo	2013 - 2014	935
DBA-3A20	BMW 328i	2013 - 2014	34
DBA-3X28	BMW 328i Granturismo	2013 - 2014	79
DBA-3A30	BMW 335i Coupe	2013 - 2014	32
DBA-3X30	BMW 335i Granturismo	2013 - 2014	49
DAA-3F30	BMW ActiveHybrid 3	2013 - 2014	239
DBA-3N20	BMW 420i	2013 - 2014	369
DBA-4A20	BMW 420i Grancoupe	2013 - 2014	47
DBA-3N28	BMW 428i	2013 - 2014	226
DBA-3R30	BMW 435i	2013 - 2014	411
DBA-4B30	BMW 435i Grancoupe	2014	8
		TOTAL	10,012