

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3586	DATE	June 4, 2015
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	Some of the subject inflators installed in frontal passenger air bag could potentially create excessive internal pressure when the air bag is deployment, which could result in the body of the inflator rupturing upon deployment. In the event of the inflator rupture, metal fragments could pass through the airbag cushion metal, which may result in injury to vehicle occupants.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GG3P	Mazda 「ATENZA」	2007	266
DBA-GG3S		2007	868
DBA-GY3W CBA-GY3W		2007	641
DBA-GGEP		2007	414
DBA-GGES		2007	195
DBA-GYEW		2007	241
		Total	