

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3624	DATE	Jul.31.2015
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain route buses with a glide slide door, there are some in which bracket which conducts the power of the air cylinder for door opening and closing and the spring pins which fixes the rotating axis making the door open and close are cracked. If the vehicle is continued to be used under the condition, in the worst case, both of the spring pins may break, resulting the door to open while driving or the switching operation of the door from the driver seat to be non-active.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-KV234L1	[HINO Blue Ribbon II]	2004～2007	422
PDG-KV234L2		2007～2010	428
PKG-KV234L2			
LKG-KV234L3		2011～2015	452
QDG-KV234L3			
QKG-KV234L3			
QPG-KV234L3			
PJ-KV234N1		2005～2007	286
PDG-KV234N2		2007～2010	337
PKG-KV234N2			
LDG-KV234N3		2010～2015	506
LKG-KV234N3			
QKG-KV234N3			
QPG-KV234N3			
		TOTAL	2,431