

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicle

<b>CAMPAIGN No.</b>	<b>3621</b>	<b>DATE</b>	<b>July. 31st, 2015</b>
<b>MANUFACTURER</b>	<b>KOBELCO CRANES CO.,LTD</b>		
<b>DESCRIPTION OF DEFECT</b>	<p>Installation of seal of hydraulic cylinder for steering apparatus of the wheel crane is wrong in direction due to workmanship error at assembling process. ; Internal seal of cylinder which seals oil from cylinder rod has been installed in the opposite direction.</p> <p>For above reason, this wrong direction seal installation may cause oil leakage because sealing for the cylinder rod will not work properly.</p>		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLE</b>
JDS-EE02	RK250-7	2012-2013	19
UDS-EE04	RK250-8	2013-2015	72
JDS-EG02	RK700	2012-2013	6
CM03	MK650	2014-2015	4
CM03L	MK650	2014	2
<b>TOTAL</b>			<b>103</b>