

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2212	DATE	2015/7/31
MANUFACTURER	FCA US LLC (Japanese Importer : FCA Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	The driver airbag inflator housing on the cars concerned may rupture, due to excessive internal pressure, during normal airbag deployment events. This condition is more likely to occur if the vehicle has been exposed to high levels of absolute humidity for extended periods of time. An inflator rupture, during airbag deployment events, could result in metal fragments striking and potentially seriously injuring the vehicle occupant(s).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
GH-LE35T	「300C Touring」	2006	253
GH-LE57T	「300C Touring」	2006	203
GH-LX35	「300C」	2005-2007	633
GH-LX57	「300C」	2005-2006	844
ABA-LE35T	「300C Touring」	2007	64
ABA-LE57T	「300C Touring」	2007	63
ABA-LX35	「300C」	2007-2008	241
ABA-LX57	「300C」	2007-2008	154
Unknown	「300C Touring」	2006	1
	「300C」	2006	1
	「300C SRT8」	2006-2007	184
	「Charger R/T」	2008	73
	「Charger SRT8」	2007-2008	171
	「Challenger SRT8」	2008	1
Total			2,886