

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	Gai-2213	DATE	2015/07/28
MANUFACTURE	MASSEY FERGUSON SA (Japanese Importer :MSK Farm Machinery Corporation CEO Toshiki Sugino )		
DESCRIPTION OF DEFECT	The retaining screws for the engine timing sensor ring may have insufficient thread locking agent because of incorrect assembly instruction.  The retaining screws may be loosened from engine vibration during driving. In the worst case, the engine timing sensor ring may be detached and the engine may be stopped and becomes unable to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-PKCPS4	MF5460-4D	2011	15
	MF5455-4D	2011	18
KDP-PKCPS4	MF6445-4D	2011	3
	MF5445-4D	2011	15
		TOTAL	51