

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3608	DATE	Jul.16.2015
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain route buses with a glide slide door, there are some in which bracket which conducts the power of the air cylinder for door opening and closing and the spring pins which fixes the rotating axis making the door open and close are cracked. If the vehicle is continued to be used under the condition, in the worst case, both of the spring pins may break, resulting the door to open while driving or the switching operation of the door from the driver seat to be non-active.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-HU2PMEA KL-HU2PMEE KL-HU2PMEEKAI	[HINO Blue Ribbon City]	2002~2005	90
KL-HU2PPEE KL-HU2PPEEKAI		2003~2005	52
ACG-HU8JLFP BJG-HU8JLFP		2005~2010	259
LJG-HU8JLGP LNG-HU8JLGP LNG-HU8JLGPKAI		2010~2015	177
ACG-HU8JMFP ACG-HU8JMFPKAI BJG-HU8JMFP		2005~2010	202
LJG-HU8JMGP LNG-HU8JMGP		2010~2015	141
		TOTAL	921