

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3599	DATE	July 9,2015
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	There is an improper electrical continuity in the electric power steering gear due to insufficient caulking at the connecting terminal between the electrical harness and the torque sensor detecting the steering effort. As a result, the warning lamp may turn on and the steering effort may increase due to termination of the power assisting function in the power steering system.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-Z21A	「COLT」	2010~2012	10,645
DBA-Z22A		2010~2012	2,651
DBA-Z21W		2010~2012	4,088
DBA-Z22W		2010~2012	1,168
DBA-Z23W		2010~2012	1,451
DBA-Z24W		2010~2012	241
CBA-Z27AG		2010~2012	1,567
		TOTAL	21,811