

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3600	DATE	July, 7, 2015
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	Due to inadequate shape of brake rods, they may contact the clutch housing or oil pipe after several times of brake pedal play adjustment. It leads to deteriorate of brake performance		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
XDN-SL1C	「SL54」	2014	68
	「SL60」	2014	49
		TOTAL	117