

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3607	DATE	Jul.17 2015
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	As to the wheel cranes, there may have the mounting bolts of the valves for functioning the suspension lock cylinders tightened with insufficient torque due to improper manufacturing process. Therefore, it may have loosened bolts due to vibration during travelling and if you continue to use the vehicle, hydraulic oil may leak through the valve mounting face, and at worst, it may lose steering of the vehicle as it use common hydraulic circuit with said valves.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
WDR-KRC013	KRM - 13H (M)	2014~2015	179	
TOTAL			179	