

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3625	DATE	August. 21. 2015
MANUFACTURER	TRANTECHS. CO. , LTD		
DESCRIPTION OF DEFECT	We have found that there are cases where the gap between the subframe construction and electrical wiring or air piping is small because of an inappropriate mounting design in the bodies of large trucks. If this should be the case, the bracket and the electrical wiring etc. may come into contact with each other due to vibration or such like while the vehicle is running, and if the vehicle is used continuously the electrical wiring etc. may be damaged. In the worst-case scenario, the engine may stall unexpectedly or the brakes may become ineffective.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KS-FW1EZWG	HINO PROFIA	2004~2005	3
KS-FW1EZWJ			
PK-FW1EZWG		2004~2005	2
ADG-FW1EZYG		2006~2007	3
BKG-FW1EZYG		2007~2009	13
BKG-FW1EZYJ			
BKG-FW1AZYG		2008	1
LKG-FW1EBBG		2010	1
LKG-FW1EZBG		2010~2012	48
LKG-FW1EZBJ			
QKG-FW1EZBG		2012~2014	35
QPG-FW1AZEG		2014	2
QPG-FW1EZEG		2014~2015	11
QPG-FW1EZEJ			
ADG-CG4YA	QUON	2005	1
ADG-CG4ZA		2005~2007	36
ADG-CG4ZE		2006	1
PKG-CG4YE		2008	1
PKG-CG4ZA		2007~2009	6
KL-CG48M	BIG THUMB	2004	1
KL-CG48R		2008	1
BKG-FS54JZ	FUSO SUPER GREAT	2008~2009	9
T O T A L			175