

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3666	DATE	Oct. 29, 2015
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	On the vehicles equipped with a vertical-type tail lift, the lock handle fitting nut of the tail lift may have been insufficiently tightened due to improper control in the manufacturing process. If a vehicle is used continuously with this condition, the nut concerned may become loose and the lock handle may come off. In the worst case, the tail lift may open while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-S500P	HIJET TRUCK	2015	68
EBD-S510P			53
		TOTAL	121